

hansgrohe


- DE** Montageanleitung
FR Instructions de montage
EN assembly instructions
IT Istruzioni per Installazione
ES Instrucciones de montaje
NL Handleiding
DK Monteringsvejledning
PT Manual de Instalação
PL Instrukcja montażu
CS Montážní návod
SK Montážny návod
ZH 组装说明
RU Инструкция по монтажу
HU Szerelési útmutató
FI Asennusohje
SV Monteringsanvisning
LT Montavimo instrukcijos
HR Uputstva za instalaciju
TR Montaj kılavuzu
RO Instrucțiuni de montare
EL Οδηγία συναρμολόγησης
SL Navodila za montažo
ET Paigaldusjuhend
LV Montāžas instrukcija
SR Uputstvo za montažu
NO Montasjeveiledning
BG Инструкция за употреба
SQ Udhëzime rreth montimit
AR تعليمات التجميع




Crometta 100 1jet
26828400 / 26829000



Crometta 100 Vario
26827400



Crometta 100 Multi
26826400



Crometta 100 1jet
26828400 / 26829000

Crometta 100 Vario
26827400

Crometta 100 Multi
26826400




P max. 0,6 MPa
6 bar

0,1 - 0,4 MPa
1 - 4 bar




T max. 60 °C


40 - 50 °C




Crometta 100 1jet 26828400



Crometta 100 1jet 26829400




Crometta 100 Vario 26827400




Crometta 100 Multi 26826400






Crometta 100 Vario
26827400
Crometta 100 Multi
26826400








94246000



	P-IX	DVGW	SVGW	ACS	WRAS	NF	KIWA
26826400	P-IX 28715/IB			X	X		
26827400	P-IX 28716/IB			X	X		
26828400	P-IX 28714/IB			X	X		
26829400	P-IX 28714/IB			X	X		





hansgrohe

Hansgrohe · Auestraße 5 · 9 · D-77761 Schiltach
Telefon +49 (0) 78 36/51-1282 · Telefax +49 (0) 7836/511440
E-Mail: info@hansgrohe.com · Internet: www.hansgrohe.com

7/2016
9.02783.03